

FIG. 1




FIG. 2




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A





FIG. 9B



094030J 0570J

[illegible]

FIG. 11

[illegible]

09940801-082901

FIG. 12

R	G	B	R	G	B	R	G	B
G	B	R	G	B	R	G	B	R
B	R	G	B	R	G	B	R	G
R	G	B	R	G	B	R	G	B
G	B	R	G	B	R	G	B	R
B	R	G	B	R	G	B	R	G

FIG. 13

G	R	B	G	R	B	G	R	B
R	B	G	R	B	G	R	B	G
G	R	B	G	R	B	G	R	B
R	B	G	R	B	G	R	B	G
G	R	B	G	R	B	G	R	B
R	B	G	R	B	G	R	B	G


FIG. 14

R	G	R	G	R	G	R	G	R
G	B	G	B	G	B	G	B	G
R	G	R	G	R	G	R	G	R
G	B	G	B	G	B	G	B	G
R	G	R	G	R	G	R	G	R
G	B	G	B	G	B	G	B	G

FIG. 15

W	G	W	R	W	B	W	G	W
R	W	B	W	G	W	R	W	B
W	G	W	R	W	B	W	G	W
R	W	B	W	G	W	R	W	B
W	G	W	R	W	B	W	G	W
R	W	B	W	G	W	R	W	B

FIG. 16



0940801 0829101

FIG.17A




FIG.17B

